

AREA	CONCERNING	Vol	Number	page
FUEL SYS	ACCELERATOR-PUMP MEASURING VIAL SOURCES	3	5	7
FUEL SYS	ACCELERATOR-PUMP NOZZLE, REMOVAL, SOLEX 40 18	18	6	11
FUEL SYS	AIR CLEANERS	13	6	12
FUEL SYS	AIR CLEANERS, SOLEX-STYLE FOR WEBERS, MAKE Y30	30	4	46
FUEL SYS	AIR CLEANERS, SOLEX, RESTORATION TIP	17	1	12
FUEL SYS	AIR CLEANERS, WOBBLY ZENITH, CURE	21	3	27
FUEL SYS	BANJO BOLT THREAD PITCH, CARB VS. PUMP	29	5	6
FUEL SYS	CARBURETION EFFECTS ON ENGINE TORQUE	24	3	34
FUEL SYS	CARBURETOR BUTTERFLIES	17	5	10
FUEL SYS	CARBURETOR BUTTERFLIES, REMOVAL CAVEAT	21	3	13
FUEL SYS	CARBURETOR COMMENTS, ZENITH & SOLEX	22	6	12
FUEL SYS	CARBURETOR ICING	15	6	35
FUEL SYS	CARBURETOR VENTURI REMOVAL	11	1	7
FUEL SYS	CHOKE CABLE REPAIR	12	3	9
FUEL SYS	DELLORTO HINTS	11	3	4
FUEL SYS	FENDER FLAP TO PROTECT FROM GAS HOSE (PRE-T13	13	1	8
FUEL SYS	FILTERS AND FILTER MAINTENANCE	27	2	19
FUEL SYS	FILTRON MATERIAL ON SOLEX BASKET-TYPE AIR CLE3	3	4	7
FUEL SYS	FLOAT LEVEL, USING A STRAW TO DETERMINE, SOLE26	26	3	17
FUEL SYS	FLOAT LEVEL, USING A SYRINGE TO DETERMINE	23	4	21
FUEL SYS	FLOAT LEVELADJUSTMENT: ZENITH & SOLEX	22	6	12
FUEL SYS	FLOAT LEVELADJUSTMENT: ZENITH & SOLEX 40 PII-4 3	3	4	6
FUEL SYS	FLOAT LEVELS, COMMENT	23	6	43
FUEL SYS	FLOAT LEVELS, SOLEX 40 PII-4	15	5	6
FUEL SYS	FLOAT VALVE OPERATION	26	4	31
FUEL SYS	FLOATS, SOLEX 40 PII-4 INTO 40PBIC CARBURETORS21	21	6	14
FUEL SYS	FLOATS, SOLEX 40 PII-4 INTO 40PBIC CARBURETORS23	23	2	14
FUEL SYS	FUEL COCK GASKET INTERCHANGE	4	3	9
FUEL SYS	FUEL COCK LEAK FROM BENT HANDLE	19	4	9
FUEL SYS	FUEL COCK LEVER COTTER PIN, TIP	25	1	43
FUEL SYS	FUEL COCK REBUILDING (356B T-6/C)	19	2	40
FUEL SYS	FUEL COCK REBUILDING (356B T-6/C), CORRECTION 19	19	3	6
FUEL SYS	FUEL COCK REMOVAL/TESTING/REPAIR	9	5	9
FUEL SYS	FUEL GAUGE SENDER GASKET INTERCHANGE	2	4	3
FUEL SYS	FUEL PRESSURE PROBLEM DUE TO PUMP-SPACER T24	24	2	12
FUEL SYS	FUEL PRESSURE PROBLEM DUE TO REBUILD-KIT SP 26	26	1	43
FUEL SYS	FUEL PUMP CAP-SCREW GASKET	5	3	6
FUEL SYS	FUEL PUMP FAILURE DUE TO LACK OF PLASTIC INSU29	29	1	54
FUEL SYS	FUEL PUMP FAILURE DUE TO PIVOT PIN LOSS, EARLY27	27	4	8
FUEL SYS	FUEL PUMP OPERATION	26	4	31
FUEL SYS	FUEL PUMP OUTLET LEAK REPAIR, LATE-STYLE	28	5	47
FUEL SYS	FUEL PUMP REPAIR (356B/C)	15	6	9
FUEL SYS	FUEL PUMP, ELECTRIC, INSTALLATION	9	4	7
FUEL SYS	FUEL PUMP, HARD STARTING DUE TO RETAINED PRE23	23	5	44
FUEL SYS	FUEL PUMP, MEASURING OUTPUT VOLUME	26	4	30
FUEL SYS	FUEL PUMPS, ELECTRIC, TIPS AND COMMENTS	20	6	31
FUEL SYS	GAS ADDITIVE	19	1	22
FUEL SYS	GAS ADDITIVE FOULING	12	3	4
FUEL SYS	GAS ADDITIVES	7	6	6
FUEL SYS	GAS ADDITIVES	8	3	10
FUEL SYS	GAS BOIL-OFF, ODOR & HARD STARTING FROM	26	4	30
FUEL SYS	GAS CAP GASKET SUBSTITUTE (356A/B)	22	4	10
FUEL SYS	GAS HOSE	26	4	45
FUEL SYS	GAS HOSE, EMERGENCY ON-THE-ROAD SPLICE	29	3	28
FUEL SYS	GAS INFO	3	4	5

FUEL SYS	GAS INFO (STODDARD, SKIRMANTS, PELLOW, ETAL) 13	13	1	5
FUEL SYS	GAS LEAD	3	2	2
FUEL SYS	GAS LEAD	13	1	11
FUEL SYS	GAS LEAK SOURCES	26	4	45
FUEL SYS	GAS OCTANE AND LEAD	7	3	5
FUEL SYS	GAS OCTANE, EXPLANATION & ENGINE REQUIREMEN22	22	6	20
FUEL SYS	GAS OCTANE, PUMP VS. ROZ, COMMENT	28	1	40
FUEL SYS	GAS SMELLAND BRAIDED GAS HOSE	26	3	40
FUEL SYS	GAS SPRAY BACK FROM CARB THROAT, POSSIBLE C 31	31	3	8
FUEL SYS	GAS TANK COLORS, BLACK VS. GREY (T-6)	23	5	11
FUEL SYS	GAS TANK COLORS, BLACK VS. GREY (T-6), EVEN FU 24	24	2	16
FUEL SYS	GAS TANK COLORS, BLACK VS. GREY (T-6), FURTHER24	24	1	16
FUEL SYS	GAS TANK COLORS, BLACK VS. GREY (T-6), UPDATE 23	23	6	12
FUEL SYS	GAS TANK REPAIR	7	4	8
FUEL SYS	GAS TANK RESTORATION	17	4	20
FUEL SYS	GAS TANK SEALER, CAVEAT	23	4	31
FUEL SYS	GAS TANK, COLLAPSED, CAUSE AND SOLUTION	23	4	31
FUEL SYS	GAS TANK, GT, FUEL COCK CAVEAT	27	2	19
FUEL SYS	GAS TANKS, GT	15	2	17
FUEL SYS	GAS TANKS, GT, UPDATE	15	3	17
FUEL SYS	GAS TANKS, LARGE CAPACITY	15	2	12
FUEL SYS	GAS TO USE	1	3	12
FUEL SYS	GAS, HISTORY; MODERN, AND COMPENSATING FOR 27	27	1	20
FUEL SYS	GAS, LEADED/UNLEADED	11	2	6
FUEL SYS	GAS, OLD AND RUSTY, COMMENTS	22	4	10
FUEL SYS	GAS, OXYGENATED	20	1	34
FUEL SYS	GROSE-JETS	9	4	6
FUEL SYS	GROSE-JETS, COMMENT	23	6	43
FUEL SYS	GROSE-JETS, COMMENT	23	2	14
FUEL SYS	HAND-THROTTLE CABLE REPAIR	27	2	24
FUEL SYS	HAND-THROTTLE LOCATION IN T-6 CARS WITH FOG L26	26	1	25
FUEL SYS	HAND-THROTTLE, FIRST (AND FINAL) APPEARANCES23	23	1	22
FUEL SYS	HAND-THROTTLE, POINT OF DISCONTINUATION	26	1	25
FUEL SYS	HAND-THROTTLES IN T-6 CARS	23	4	12
FUEL SYS	HAND-THROTTLES IN T-6 CARS, ADDITIONAL COMME25	25	6	24
FUEL SYS	HESITATION WITH LIGHT THROTTLE APPLICATION WH27	27	5	12
FUEL SYS	HOT-START PROBLEMS FROM HEAT-SOAKED CARBU23	23	5	43
FUEL SYS	IDLE JET SIZES	7	1	6
FUEL SYS	LEAK FINDER	23	1	33
FUEL SYS	LINKAGE, FROZEN	2	1	3
FUEL SYS	MAIN JET TRICK FOR HILLCLIMBS	24	4	33
FUEL SYS	NEEDLE VALVE, STUCK, SOLEX 40 PII-4	18	6	11
FUEL SYS	NEEDLE VALVE, STUCK, SOLEX 40 PII-4	24	5	16
FUEL SYS	NEEDLE VALVES	23	5	44
FUEL SYS	SOLEX 26 VFJ CARBS	31	3	14
FUEL SYS	SOLEX 40 PII-4 ADJUSTMENT	26	5	28
FUEL SYS	SOLEX 40 PII-4 FLAT SPOT	4	2	7
FUEL SYS	SOLEX 40 PII-4 IDLE PROBLEMS CAUSED BY THROTT26	26	1	10
FUEL SYS	SOLEX 40 PII-4 REBUILDING	17	2	10
FUEL SYS	SOLEX 40 PII-4 VINDICATION	16	1	7
FUEL SYS	SOLEX IDLE-JET SOURCE	5	1	4
FUEL SYS	SOLEX THROTTLE-SHAFT REPAIR SOURCES	5	3	6
FUEL SYS	THROTTLE BELL-CRANK ADJUSTMENT	3	4	22
FUEL SYS	THROTTLE LINKAGE ADJUSTMENT	9	5	10
FUEL SYS	THROTTLE LINKAGE ADJUSTMENT	12	6	10
FUEL SYS	THROTTLE LINKAGE FREE-PLAY REMOVAL, "FACTOR 31	31	6	21

FUEL SYS	THROTTLE LINKAGE INTERFERENCE WITH ZENITH AI29	29	2	50
FUEL SYS	THROTTLE LINKAGE LUBRICATION	25	3	22
FUEL SYS	THROTTLE LINKAGE SERVICING (356A/B/C)	25	5	20
FUEL SYS	THROTTLE LINKAGE, "COAT HANGER" WELDING CAV 28	28	1	38
FUEL SYS	THROTTLE LINKAGE, STUCK IN HIGH HEAT	29	2	50
FUEL SYS	THROTTLE RETURN SPRING PLACEMENT	16	3	9
FUEL SYS	THROTTLE RETURN SPRING, ADDITIONAL	14	5	8
FUEL SYS	THROTTLE ROD, TRANS TO ENGINE, CORRECT INSTA24	24	1	12
FUEL SYS	TUNE-UP, GENERAL SYSTEM	20	6	30
FUEL SYS	VINTAGE RACING FUEL COMMENT	21	1	11
FUEL SYS	VINTAGE RACING PREPARATION	20	6	14
FUEL SYS	VINTAGE RACING PREPARATION	21	1	10
FUEL SYS	WATER IN TANK	11	1	8
FUEL SYS	WEBER ADAPTER-PLATE GASKETS	8	1	7
FUEL SYS	WEBER LEAD PLUGS, LEAKS FROM	27	2	24
FUEL SYS	WEBER UNI-SYN ADAPTER	9	6	7
FUEL SYS	WEBERS, SKIRMANTS' COMMENTS	14	3	6
FUEL SYS	WEBERS, TUNING WITH AN EXHAUST GAS ANALYZER31	31	2	60
FUEL SYS	ZENITH "WET LOOK"	17	2	10
FUEL SYS	ZENITH ACCELERATOR PUMPS	2	1	3
FUEL SYS	ZENITH ACCELERATOR PUMPS	5	6	5
FUEL SYS	ZENITH AIR CORRECTION JET, REMOVAL FROM COM 24	24	3	37
FUEL SYS	ZENITH AIR FILTER CAN, KNECHT ID PLATE, PHOTO	21	1	12
FUEL SYS	ZENITH AIR FILTER CANS	5	6	5
FUEL SYS	ZENITH BODY REPAIR	2	3	4
FUEL SYS	ZENITH BRASS PLUG REPLACEMENT	11	1	7
FUEL SYS	ZENITH CARBS, IDing, REBUILDING, TUNING AND CO 31	31	4	58
FUEL SYS	ZENITH CARBURETOR LEAKS	2	2	10
FUEL SYS	ZENITH COMMENTS	21	6	11
FUEL SYS	ZENITH FLOAT-LEVEL, CHECKING OFF THE CAR WITH29	29	2	50
FUEL SYS	ZENITH FLOAT-LEVEL, COMMENTS	21	6	11
FUEL SYS	ZENITH FLOATS, STUCK	21	6	11
FUEL SYS	ZENITH GAS SEEPAGE	1	3	13
FUEL SYS	ZENITH IDLE MIXTURE SCREWS, INSTALLATION CAR 18	18	6	11
FUEL SYS	ZENITH OVERHAUL	15	6	8
FUEL SYS	ZENITH PLUG, SOURCE	11	4	9
FUEL SYS	ZENITH SIGHT-LEVEL GAUGE	16	3	9
FUEL SYS	ZENITH SOFT PLUGS	1	5	4
FUEL SYS	ZENITH TOP-SCREW REPAIR CLARIFICATION	16	3	9
FUEL SYS	ZENITH, PRIMING DRY FLOAT BOWL	18	2	19